

## 6.0 LITER VARIATIONS

DUE TO THE MANY VARIATIONS AND VIN # DISCREPANCIES WITH THE 6.0, IT IS THE INSTALLER'S RESPONSIBILITY TO MAKE SURE THE REMANUFACTURED LONG BLOCK IS CONFIGURED THE SAME AS THE LONG BLOCK YOU ARE REPLACING. OUR WARRANTY WILL NOT COVER THESE ISSUES ONCE THE ENGINE IS INSTALLED IN THE VEHICLE.

**MAKE SURE YOU HAVE LIKE FOR LIKE BEFORE YOU INSTALL THE ENGINE.**

