

# TECHNICAL SERVICE BULLETIN

# BLACKWATER

# ENGINES

TSB #:	TB-RV 0813	ENGINE:	DT 466E 12 VALVE-469H-470H
DATE:	10/28/2013	REVISION:	


## DT 466E 12 VALVE, 469H, 470H SERIES BULLETIN

DUE TO THE VARIATIONS IN THE RELIEF VALVES ON THE DT ENGINES, CARE MUST BE TAKEN TO PUT THE CORRECT VALVE IN THE CORRECT LOCATION.

INSTALL THE RELIEF VALVE SUPPLIED WITH THE "FC" MARKING IN THE FRONT COVER



INSTALL THE RELIEF VALVE SUPPLIED WITH NO MARKINGS ON THE PASSENGER SIDE OF THE BLOCK UNDER THE OIL COOLER HOUSING.



INSTALL THE RELIEF VALVE WITH THE "FC" ON IT IN THIS LOCATION.



INSTALL THE RELIEF VALVE WITH NO MARKINGS IN THIS LOCATION

ALL NECESSARY RELIEF VALVES ARE INCLUDED IN THE GASKET SET.