## **TECHNICAL SERVICE BULLETIN**

TSB #:	DRR-06222015	ENGINE:	6.6L Duramax
DATE:	06/22/2015	REVISION:	2/2/2017



## DURAMAX CAMSHAFT DISTRIBUTOR RING

All Duramax long blocks require the distributor ring to be transferred from the original cam gear or replaced.

General Motors part numbers 97367477 or 97226118, depending on the application.



PART # 97367477 2 PIECE CAM GEAR PART # 97226118 1 PIECE CAM GEAR