

TECHNICAL SERVICE BULLETIN

| | | | |
|---------|--------------|---------|-----------------------------------|
| Part #: | DDR-06222015 | Engine: | 6.6L Duramax |
| Date: | 06/22/2015 | Title: | Duramax Camshaft Distributor Ring |

All Duramax long blocks require the distributor ring to be transferred from the original cam gear or replaced. General Motors part numbers 97367477 or 97226118, depending on the application.

PART # 97367477
2 PIECE CAM GEAR



PART # 97226118
1 PIECE CAM GEAR

