

Blackwater Engines No Fault Warranty

The Blackwater Engines No Fault Warranty is a policy that mirrors the existing time, mileage and labor coverage of the standard Blackwater Engines warranty originally included with the unit. The Blackwater Engines. This warranty gives the customer peace of mind that previously denied claims due to freight damage, installation errors or related vehicle component part failures will be covered.

ADDITIONAL COVERAGE INCLUDED:

The no fault warranty covers the first time non-manufacturing responsible defect for the unit value and installation labor up to the original coverage timeline.

Dry start, foreign object damage, lack of lubrication, over speed, cracked head or block, detonation or pre-ignition, overheating and shipping damage are all examples of covered failures under the no fault service agreement.

The Blackwater Engines No Fault Warranty upgrade adds coverage for towing, rental car, fluids, and additional labor coverage for unit installation.

TOWING: Towing will be covered up to a maximum of \$100.00. Customer must supply a copy of the invoice from the towing company.

RENTAL: Car rental will be covered up to 10 days at \$35.00 per day maximum. Customer must supply a copy of the rental contract.

FLUIDS: Fluid replacement will be covered up to \$50.00 total.

LABOR: Hourly rates for all authorized repairs will be paid in accordance with the rate that was paid for the original installation. The hourly rate reimbursed may not exceed \$100.00 per hour at ALLDATA time.

WHAT IS EXCLUDED:

Parts and labor warranty under the no fault agreement is limited to the first time failure of the assembly. Multiple failures due to non-manufacturing defects are not covered. Engines or transmissions that are used in a manner that violates the terms of the standard warranty or used for purposes other than their original intended use is not covered. Do-it yourself repairs and repairs performed by unlicensed repair facilities are not covered. Transmission claims on vehicles with EGR deletes, DPF deletes or have programmers/aftermarket controllers installed.