

TECHNICAL SERVICE BULLETIN

Part #:	VAR-01012017	Engine:	6.0L Powerstroke & VT365 Navistar
Date:	01/14/2021	Title:	6.0L Variation

INVOICE #:

PART #:

BUILD DATE:

APPROVED BY:

FIRST STYLE BRANCH




THREADED STAND PIPE CONNECTION PART #1840550C1

SECOND STYLE BRANCH



PRESS IN O-RING CONNECTION PART # 1843351C2

THIRD STYLE BRANCH



NEW STYLE HPOP JUNCTION PART # 1843351C3

1ST STYLE INJECTOR CLAMP



PART# 1838901C3, 1838901C4 & OTHERS BOLTS ONTO ROCKER BOX
 # 1840550C1 (1ST)
 # 1843351C2 (2ND)
 # 1843351C3 (3RD)

2ND STYLE INJECTOR CLAMP



FORD PART# 1856237C1 & OTHERS BOLTS ONTO ROCKER BOX # 1858473C1 (4TH)

1ST STYLE OIL MANIFOLD



THE FIRST STYLE OIL MANIFOLD ONLY BOLTS CORRECTLY ON TO THE ROCKER

2ND STYLE OIL MANIOLD



THE SECOND STYLE OIL MANIFOLD BOLTS ONTO ROCKER BOX PART
 # 1843351C2,
 # 1843351C3,
 & # 1858473C1