

TECHNICAL SERVICE BULLETIN

Part #:	VAR-01012017	Engine:	6.0L Powerstroke & VT365 Navistar
Date:	01/14/2021	Title:	6.0L Variation


INVOICE / WORK ORDER#:

PART #:

BUILD DATE:

APPROVED BY:

FIRST STYLE BRANCH



THREADED STAND PIPE CONNECTION PART #1840550C1

SECOND STYLE BRANCH



PRESS IN O-RING CONNECTION PART # 1843351C2

THIRD STYLE BRANCH



NEW STYLE HPOP JUNCTION PART # 1843351C3


1ST STYLE INJECTOR CLAMP



2ND STYLE INJECTOR CLAMP



1ST STYLE OIL MANIFOLD



2ND STYLE OIL MANIOLD



PART# 1838901C3, 1838901C4 & OTHERS BOLTS ONTO ROCKER BOX
 # 1840550C1 (1ST)
 # 1843351C2 (2ND)
 # 1843351C3 (3RD)

FORD PART# 1856237C1 & OTHERS BOLTS ONTO ROCKER BOX # 1858473C1 (4TH)

THE FIRST STYLE OIL MANIFOLD ONLY BOLTS CORRECTLY ON TO THE ROCKER BOX PART # 1840550C1

THE SECOND STYLE OIL MANIFOLD BOLTS ONTO ROCKER BOX PART # 1843351C2, # 1843351C3, & # 1858473C1